



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

February 1, 2006

Supervisor 10071

**Mine Name:** B & C Limestone Quarry  
**Operator Name:** Bryce Haas

**Permit number:** M/039/013  
**Inspection Date:** August 18, 2005  
**Time:** 9:00 am

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** Bryce Haas, Operator  
**Mine Status:** Active

**Weather:** Clear, warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This inspection was done to Check on status of recent reclamation.

#### Inspection Summary:

1. The operator has been operating under a Division Directive to reduce the area effected by this operation through reclamation work in order for the reclamation surety amount currently held by the Division to be adequate to complete reclamation of the site. The operator has been struggling financially and cannot increase the size of his surety. During this inspection, we discussed the recent filing of reorganization bankruptcy. The operator is hopeful to get his finances in order.
- 6 & 9. Over the past several months, the operator has reclaimed approximately 13.3 acres. Including regrading, topsoil replacement and seeding. Approximately 13.6 acres remain as part of the active mine. The Division Directive required approximately 12.5 acres be reclaimed. The roughness was good, however with the dry summer, little has germinated. There were no obvious signs of erosion of the reclaimed portion. Of concern, an oil company had set up camp an a portion (2-3 acres) of the reclaimed area and had impacted (compacted) the area with equipment. This was reported to the Oil and Gas manager to assure that the oil company properly restores this area.


Mr. Haas indicated that he intends to continue with reclamation efforts to reduce the disturbed area to approximately 5 acres. It is unlikely that this site will expand in the future due to the lack of viable rock outside the current disturbed area.

Inspection Date: September 18, 2005; Report Date: February 1, 2006  
Page 2 of 2  
M/039/013

**Conclusions and Recommendations:**

Continue to monitor this site when in the area.

**Inspector's Signature**



**Date:** February 1, 2006

LK:pb

O:\M039-Sanpete\m0390013-BandCLimestone\inspections\insp-08182005.doc